

AQUO PLANK®



WHITSUNDAYS XL

Signature
signaturefloors



WHITSUNDAYS1140 Hamilton Oak



WHITSUNDAYS1141 Brampton Oak



WHITSUNDAYS1143 Long Island Oak



WHITSUNDAYS1144 Hayman Oak



WHITSUNDAYS1147 Daydream Oak

TECHNICAL SPECIFICATIONS

Plank Size	238 x 1800 x 12mm
Edge Design	V groove 4 sides
Finish	Matt Power-Seal™ all edges
Wear Layer Treatment	Clear enhanced UV cured coating
Wear Class	AC4 commercial-grade quality
Core	Ultra Stable SureCore™ - provides 60% more stability
Technology	AtroGuard™ 'Water-Resist' Technology
Planks per Box	3 pcs/box (1.28m ²)
Features	Superior pattern repeat Impact, indent, stain, scratch & water resistant Slip, fire, wear & fade resistant
Fire Rating	Suitable all areas (>4.5kW/m ² CRF)
Installation	Tight Lock™ - minimum sub-floor preparation required* Install up to 400m ² without transition strips Install in dry & wet areas - see installation guides
Heating	Suitable for underfloor heating
Environment	Contains 0% plastic elements
Warranty	Lifetime Residential, 12 Yr Light Commercial



au 1800 150 554
nz 0800 150 555
signaturefloors.com.au
signaturefloors.co.nz

*Inspect your sub-floor before you begin. It must be clean, dry and level to 5mm within a 3m span.

Terms & Conditions: Specifications are subject to manufacturing tolerances and may be changed without prior notice. Dye lots may vary in colour from sample and between production lots. All product purchases are subject to Signature Floorcoverings Standard Terms & Conditions of Sale. Please refer to our Installation Guideline, Maintenance Manual and Warranty Document for further clarification.

This warranty is in addition to and does not affect your statutory rights. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law/NZ Consumer Guarantees Act 1993. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.